

Geometrical and geotechnical characterization of the earth fissures appeared in the Guadalentín Valley (southeastern Spain) after the September 2012 flooding

J.L. Pastor¹, J. Mulas², R. Tomás¹, G. Herrera², J.A. Fernández-Merodo², M. Béjar-Pizarro², L. Jordá³, J.C. López-Davalillos², R. Aragón², R.M. Mateos²

¹ Department of Civil Engineering. University of Alicante, P.O. Box 99, E-03080 Alicante, Spain.

² Grupo de Riesgos Geológicos, Departamento de Investigación y Prospectiva Geo-científica, Instituto Geológico y Minero de España (IGME), Ministerio de Economía y Competitividad, c/ Alenza 1, E-28003 Madrid, Spain.

³ Departamento de Ingeniería y Morfología del Terreno, Universidad Politécnica de Madrid, c/ Prof. Aranguren nº 3, Ciudad Universitaria, 28040 Madrid, Spain

Correspondence to: J.L. Pastor (joseluis.pastor@ua.es)

Abstract. Two earth fissures appeared in Murcia province (SE Spain) after the flood occurred because of a heavy downpour on 28th September 2012. In this area, located within the Guadalentín Valley, up to 212 litres per square metre were reported that day. More than 200 agricultural exploitations were destroyed by the flooding, having a devastating effect on many infrastructures, such as a main A-7 highway bridge that collapsed in this event. The earth fissures appeared after this flooding in the towns of Puerto Lumbreras and Totana. The first fissure showed a straight-line direction approximately parallel to the main geological structures of the Guadalentín Valley. The total length of the fissure was 400 m and was 2 to 3 m depth. The soil in the fissure is classified as a low plasticity silt with some sand and clay, ML, according to the Unified Soil Classification System. From the sieve and hydrometer tests, the percentage of silt in these samples were between 48-68%, the clay content between 12-30% and the sand content between 2-40%. The plasticity index was smaller than 9.2 for all the samples. To evaluate the piping and internal erosion susceptibility of the soil, pinhole, crumb and geochemical tests were done to the collected samples. A result of non-dispersive soil was obtained from Crumb and Pinhole tests. Nevertheless, the pH, Sodium Adsorption Ratio and Exchangeable Sodium Percentage tests showed that some samples could be affected by the dispersion of the soil. Also, the collapsible potential of the soil was studied showing negative results for all the samples except for that collected at the south end of the fissure which showed a medium to high potential. Concerning the Totana fissure, it appeared with different branches and holes instead of as a rectilinear pattern. The total length of the fissure was 190 m, being the soil characterized as a silty soil. Lastly, INSAR data, GPS, GPR and land subsidence maps were used to study the possible origin of these fissures.

1 Introduction

Earth Fissures are open ground fractures that form in unconsolidated sediments as the result of tensional stresses applied in the ground. These fissures are usually associated with land subsidence due to water withdrawal (Arizona Geological Survey, 2019.; Schumann and Poland, 1970). This kind of fissures associated with land subsidence has been reported in many places around the world, as in Arizona (U.S.A.) (Jachens and Holzer, 1982), Saudi Arabia (Bankher and Al-Harhi, 1999) or China (Zhang et al., 2008; Hu et al., 2019) amongst others. In all these cases, the fissures appeared in arid and semi-arid lands.

The soil affected by the earth fissure in the Saudi Arabia case (Bankher and Al-Harhi, 1999) was a Quaternary alluvium soil classified as a low plasticity silt. This soil showed some collapsibility potential. The geophysical investigation done in this case indicated that the open earth fissures were located above ridges and steps of the buried bedrock surface, where the aquifer alluvium thins. Moreover, the fissures were opened and enlarged by flood erosion. Regarding the case reported by Zhang et al. (2008) in China, the earth fissures affected Quaternary deposits of alluvial, lacustrine, marine and palustrine types, formed by clay, silty clay, silt, sand and gravel. In this case, the earth fissures mainly occurred in belts. These belts were formed by a main fissure, 3 to 6 cm width, and several subordinates' fissures on both sides of the main one. An extensive area affected by subsidence was studied. Earth fissures were detected only in the zone where the bedrock tectonics is complex, including several folds and faults, and some buried scarps that change abruptly the thickness of the Quaternary deposits. In other zones of the study, such as Shanghai or Suzhou, the bedrock basement is deeper and changes smoothly. No earth fissures were detected on these zones, although the total subsidence was bigger here than in the other zones.

Also in the case reported by Jachens and Holzer (1982) in Arizona, all of the fissures zones occurred above either

ridges or steps in the bedrock features. This seems to be a common pattern in subsidence areas where fissures have appeared.

In this study, the two earth fissures that developed after a flood event in Guadalentín Valley (Murcia, SE Spain) have been both geometrically and geotechnically characterized. The purpose of this characterization was to know the soil properties where the cracks were open and to define the cracks' geometry. This information, together with that provided by future research, could help to understand the cause of the earth fissures appeared after the flood.

The flooding was caused by an intense rainfall that lasted three days accumulating up to 212 mm per square meter. This event caused 10 fatalities (3 in the near area to Puerto Lumbreras fissure), destroyed more than 200 agricultural exploitations and had a catastrophic impact to many infrastructures, collapsing, amongst others, a main highway bridge.

2 Materials and methods

The geometrical and geotechnical characterization of both fissures was done in two stages: 1) Mapping the fissures using a GPS in the field and 2) Collecting soil samples from within the fissures to analyze them in the laboratory. In addition to mapping the fissure, a Ground Penetrating Radar (GPR) was used near both fissures to detect possible anomalies in the first meters of depth.

Regarding the laboratory tests performed to characterize the soil, five samples were collected in the Puerto Lumbreras fissure by the Geological Survey of Spain performing the following tests: a) particle size distribution (sieve and hydrometer); b) Atterberg limits; c) free swell index; d) collapsibility index; e) pinhole, Crumble and double hydrometer; f) sulfates content; g) sodium adsorption ratio; and h) exchangeable sodium percentage. In addition, one sample was collected to characterize the soil within the Totana fissure. Soil classification tests (sieve analysis, hydrometer and Atterberg Limits) and soil

dispersion tests (pinhole, Crumble and double hydrometer) were performed on this sample.

3 Results and discussion

The mapping of the Puerto Lumbreras earth fissure is shown in Figure 1, modified from Mulas (2013). This figure shows the distribution of the fissure that appeared when waters receded on a very flat land. The main crack was about 400 m long and was perpendicular to the main flow of the flood, except for the northern section of the crack where it was nearly parallel to the flow. The crack presented a main NW-SE orientation (N150E) that changes to E-W in the northern section.

It is important to point out that the continuity of the earth fissure was disrupted by the road located at the center of the figure which presents a lower elevation. The orange points in Figure 1 indicate those locations in which signs

of piping were recognized in the field (Figure 2) and the green triangles indicate the locations from which soil samples were collected to be tested later in the laboratory. During the field inspection, a damaged ditch was observed beside the aforementioned road after the flooding. This road was approximately parallel to the main flow of the flood and some erosion was clearly observed below the ditch.

A GPR was used along the ditch beside the road to analyze what was beneath the concrete (Figure 3). The contact between the natural soil and the filling is observed in this figure. A water pipe was also detected, as well as some loss of signal that can be due to soil erosion. However, no good information was obtained below 1.5 to 2.0 m, probably due to the silty clay composition of the soil. Figure 4 shows an aerial view of the northern section of the crack and the runoff flow direction. Note how the fissure intersects and surrounds the building. Figure 5 shows the location in




Figure 1: Location of the Puerto Lumbreras earth fissure and the location of signs of piping and samples collection. Modified from Mulas (2013). Derivative work from PNOA 2019 CC-BY scene.es.

which the direction of the fissure changed from NE-SW to E-W. The aperture of the fissure can be seen in this figure. The fissure showed rough and vertical sides with a maximum depth of 3.7 m and a maximum aperture of 2.7 m.



Figure 2: Signs of piping along the fissure. Soil erosion caused by water beneath the surface of the ground creating an underground tunnel.




Figure 3: Ground Penetrating Radar along the ditch beside the road.

As said above, for the geotechnical characterization, five soil samples were collected along the Puerto Lumbreras fissure. These samples were collected at the surface of the ground at several points along the main crack. According to the particle size distribution, the samples had a silt content between 48 and 68%, a clay content between 12 and 30% and a sand content between 2 and 40%. In all the samples, the plasticity index was lower than 9.2. Therefore, the samples were classified as a low plasticity silt (ML) according to the Unified Soil Classification System (USCS). The clay minerals of the soil were mainly of the illite type. The result of the tests showed that the soil was neither expansive nor collapsible, except for one of the five samples which exhibited a medium to high collapsibility. The soil also showed a low content of sulfates, between 0.03 and 0.20%. Regarding the

dispersion tests, Crumb, Double hydrometer and Pinhole tests showed a non-dispersive soil. Finally, the Sodium Absorption Ratio obtained in the tests was between 0.8 and 8.8 and the Exchangeable Sodium Percentage between 1.9 and 14.4%. Therefore, these results show a non-dispersive soil for most of the samples, except for two of them which had a result of slightly to moderate dispersive soil. The non-dispersive results discard the clay particles dispersion into water and the later remobilization as the origin of the crack.

Regarding the Totana earth fissure, the location and distribution of the fissure observed when water receded can be seen in Figure. Figure shows a view of the fissured appeared in Totana. The fissure appeared on a flat land and



Figure 4: Aerial view of the northern section of the crack (courtesy of Puerto Lumbreras City Council). The yellow arrows indicate the location of the earth fissure. Modified from Mulas (2013).



Figure 5: Aerial view of the 3rd and 2nd northern section of the crack (courtesy of Puerto Lumbreras City Council). The yellow arrows indicate the location of the earth fissure. Modified from Mulas (2013).

was discontinuous and ramified. Both soils, in Totana and Puerto Lumbreras, have a similar origin, a distal alluvial fan, although the age of the soils in Totana is older than in Puerto Lumbreras, Late or Upper Pleistocene (more than 10,000 years ago) in Totana and Holocene (less than 10,000 years ago) in Puerto Lumbreras. Some signs of piping were also observed in this fissure and one sample was collected at the site to test it later in the laboratory. The results of the tests show sand, silt and clay of 25, 53 and 22%, respectively. The liquid limit was 31.8 and the plasticity index 8.3. Therefore, the soil was classified as a low plasticity silt (ML) according to the USCS. The results to assess the soil dispersion (Crumb, Double Hydrometer and Pinhole tests) showed a non-dispersive soil.



Figure 7: Image of the fissure appeared in Totana.




Figure 6: Location of the Totana earth fissure and the location of signs of piping and samples collection. Derivative work from PNOA 2019 CC-BY scene.es.

According to the hydrogeological scheme of the Guadalentín valley (Cerón and Pulido-Bosch, 1996), the borders of the valley are formed by Perm-Triassic and Miocene materials. The basin filling is composed of gravels, clays and silts reaching up to 400 m thickness. The same authors performed a geoelectrical prospection to define the Plio-Quaternary thickness isolines and the main faults of the substratum. The cross-section of the valley showed in that section indicated the existence of a graben structure. This kind of structure, where fault blocks are downthrown relative to their surroundings, can generate earth fissures due to differential land subsidence (Schumann and Poland, 1970; Zhang et al., 2008).

Figure shows an SAR interferometry deformation map derived from an Envisat dataset covering the period 2003 – 2010, where the location and main direction of the fissures have been drawn. As can be seen, both fissures are located near the edge of the subsidence bowl. It is worthy to point out that this valley presents the highest subsidence rate due to groundwater extraction in Europe with accumulated settlements up to 2,5 m from 1992 to 2012 (Bonì et al., 2015).

The direction of one of the main geological structures of the Guadalentín Valley can be seen in Figure 8. The other main direction is perpendicular to the first one (Cerón, 1997). Therefore, the direction of both fissures are




Figure 8: Location of both fissures on the deformation map of Guadalentín Valley from Envisat 2003-2010.

approximately parallel to one of the directions of these main geological structures or faults in this area.

It should be mentioned that earth fissures reported in previous research due to subsidence have also appeared after high-intensity rainstorms because of the flood erosion (Bankher and Al-Harhi, 1999; Schumann and Poland, 1970) and, thus, this could be the possible origin of the earth fissures studied in this work.

4 Conclusion

Two earth fissures were detected after a flood occurred because of a heavy downpour in Guadalentín Valley. In both cases, the fissures appeared in a very flat area after waters receded. Signs of piping were observed along the fissures which affected low plasticity silty soils. These soils showed low collapsibility potential in nearly all the tests and were classified as non-dispersive soils. The high subsidence rate of the area and the direction of the geological structures of the valley suggest that these fissures could be related to land subsidence. However, further studies are required to confirm this hypothesis.

5 Acknowledgements

This project has been partially funded by the EU project RESources managEment by integrating eaRth observation deriVed monitoring and fLOW modelling (RESERVOIR; G.A. N° 1924), supported by the University of Alicante (GRE17-11 and GRE18-15 Projects), the Spanish Ministry of Economy and Competitiveness, the State Agency of Research and the European Funds for Regional Development under project TEC2017-85244-C2-1-P and the UNESCO ICGP641 project.

References

Arizona Geological Survey: Earth Fissures & Ground Subsidence, AZGS, [online] Available from: <https://azgs.arizona.edu/center-natural-hazards/earth-fissures-ground-subsidence> (Accessed 22 August 2019).

Bankher, K. A. and Al-Harhi, A. A.: Earth Fissuring and Land Subsidence in Western Saudi Arabia, *Nat. Hazards*, 20(1), 21–42, doi:10.1023/A:1008167913575, 1999.

Boní, R., Herrera, G., Meisina, C., Notti, D., Béjar-Pizarro, M., Zucca, F., González, P. J., Palano, M., Tomás, R., Fernández, J., Fernández-Merodo, J. A., Mulas, J., Aragón, R., Guardiola-Albert, C. and Mora, O.: Twenty-year advanced DInSAR analysis of severe land subsidence: The Alto Guadalentín Basin (Spain) case study, *Eng. Geol.*, 198, 40–52, doi:10.1016/J.ENGCEO.2015.08.014, 2015.

Cerón, J. C.: Hidrogeoquímica del acuífero del alto Guadalentín (Murcia), edited by Consejería de Medio Ambiente Agricultura y Agua de la Región de Murcia, Murcia, Spain., 1997.

Cerón, J. C. and Pulido-Bosch, A.: Groundwater problems resulting from CO₂ pollution and overexploitation in Alto Guadalentín aquifer (Murcia, Spain), *Environ. Geol.*, 28(4), 223–228, doi:10.1007/s002540050096, 1996.

Jachens, R. C. and Holzer, T. L.: Differential compaction mechanism for earth fissures near Casa Grande, Arizona, *Geol. Soc. Am. Bull.*, 93(10), 998–1012, doi:10.1130/0016-7606, 1982.

Hu, L., Dai, K., Xing, C., Li, Z., Tomás, R., Clark, B., Shi, X., Chen, M., Zhang, R., Qiu, Q. and Lu, Y. 2019. Land subsidence in Beijing and its relationship with geological faults revealed by Sentinel-1 InSAR observations. *International Journal of Applied Earth Observation and Geoinformation*, 82, 101886, doi: <https://doi.org/10.1016/j.jag.2019.05.019>.

Mulas, J.: Las espectaculares grietas de Puerto Lumbreras, *Enseñanza las Ciencias la Tierra*, 21(2), 223–225, 2013.

Schumann, H. H. and Poland, J. F.: Land Subsidence, Earth Fissures and Groundwater Withdrawal in South-Central Arizona, U.S.A., in *Symposium on Land Subsidence*, edited by International Association of Scientific Hydrology, IASH / AIHS - Unesco, Tokyo., 1970.

Zhang, Y., Xue, Y.-Q., Wu, J.-C., Yu, J., Wei, Z.-X. and Li, Q.-F.: Land subsidence and earth fissures due to groundwater withdrawal in the Southern Yangtse Delta, China, *Environ. Geol.*, 55(4), 751–762, doi:10.1007/s00254-007-1028-8, 2008.